

03500.010106.6

PATENT

Cole
4

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

TOSHIKAZU OHNISHI ET AL.

Appl. No.: 10/776,171

Filed: February 12, 2004

For: ELECTRON-EMITTING DEVICE,
ELECTRON SOURCE, AND
IMAGE FORMING APPARATUS

U.S. Patent No.: 6,890,231 B2

Issued: May 10, 2005

Examiner: Joseph L. Williams

Group Art Unit: 2879

Certificate
FEB 14 2006
of Correction

February 8, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

02/10/2006 HALI11 00000003 6890231


01 FC:1811

100.00 OP

FEB 15 2006

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Frank A. DeLucia
Attorney for Patentees
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

NY_MAIN 518364v1

FEB 15 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,890,231 B2

DATED : May 10, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE (75) INVENTORS

"Toshikazu Ohnishi, Tokyo (JP);
Masato Yamanobe, Tokyo (JP); Ichiro
Nomura, Kanagawa-ken (JP);
Hidetoshi Suzuki, Kanagawa-ken (JP);
Yoshikazu Banno, Kanagawa-ken (JP);
Takeo Ono, Tokyo (JP); Masanori
Mitome, Kanagawa-ken (JP)"
should read --Toshikazu Ohnishi, Machida (JP);
Masato Yamanobe, Machida (JP); Ichiro
Nomura, Atsugi (JP);
Hidetoshi Suzuki, Fujisawa (JP);
Yoshikazu Banno, Ebina (JP);
Takeo Ono, Machida (JP); Masanori
Mitome, Yokohama (JP)--.

COVER PAGE (56) FOREIGN PATENT DOCUMENTS

"1283749 A" should read --1-283749 A--; and
"01292728 A should read --1-292728 A--.

COVER PAGE (56) OTHER PUBLICATIONS

"Patent Abstracts of Japan, vol. 14, No. 1 08 (E-896)(4151), Feb. 27, 1990." should
read --Patent Abstracts of Japan, vol. 14, No. 1 08 (E-896)(4051), Feb. 27,
1990.--.

COLUMN 1

Line 32, ""PHYSICAL Properties of thin-film field emission cathodes" should read
--"Physical Properties of Thin-Film Field Emission Cathodes--;
Line 33, "with molybdenum cones"," should read --with Molybdenum Cones",--;
Line 35, "tunnel-emission amplifier"," should read --Tunnel-Emission
Amplifier",--; and
Line 45, "In₂O₃/SnO₂" should read --In₂O₃/SnO₂--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,890,231 B2

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

NY_MAIN 518364v1



FEB 15 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,890,231 B2

DATED : May 10, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5

Line 25, "incorporation" should read --incorporating--.

COLUMN 6

Line 46, "manometer" should read --nanometer--.

COLUMN 8

Line 66, "an" should read --a--.

COLUMN 9

Line 65, "greater" should read --greater than--.

COLUMN 10

Line 38, "to" should read --to as--.

COLUMN 11

Line 28, "cross sectional" should read --cross-sectional--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,890,231 B2

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies
@ 30¢ per page



Form PTO 1050 (Rev. 3-82)

NY_MAIN 518364v1

FEB 15 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,890,231 B2

DATED : May 10, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15

Line 3, "denotes" should read --denote--; and
Line 66, "byway" should read --by way--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 518364v1

PATENT NO. 6,890,231 B2

No. of add'l. copies
@ 30¢ per page



FEB 15 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,890,231 B2

DATED : May 10, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE (75) INVENTORS

“Toshikazu Ohnishi, Tokyo (JP);
Masato Yamanobe, Tokyo (JP); Ichiro
Nomura, Kanagawa-ken (JP);
Hidetoshi Suzuki, Kanagawa-ken (JP);
Yoshikazu Banno, Kanagawa-ken (JP);
Takeo Ono, Tokyo (JP); Masanori
Mitome, Kanagawa-ken (JP)”

should read --Toshikazu Ohnishi, Machida (JP);
Masato Yamanobe, Machida (JP); Ichiro
Nomura, Atsugi (JP);
Hidetoshi Suzuki, Fujisawa (JP);
Yoshikazu Banno, Ebina (JP);
Takeo Ono, Machida (JP); Masanori
Mitome, Yokohama (JP)--.

COVER PAGE (56) FOREIGN PATENT DOCUMENTS

“1283749 A” should read --1-283749 A--; and
“01292728 A should read --1-292728 A--.

COVER PAGE (56) OTHER PUBLICATIONS

“Patent Abstracts of Japan, vol. 14, No. 1 08 (E-896)(4151), Feb. 27, 1990.” should
read --Patent Abstracts of Japan, vol. 14, No. 1 08 (E-896)(4051), Feb. 27,
1990.--.

COLUMN 1

Line 32, ““PHYSICAL Properties of thin-film field emission cathodes” should read
--“Physical Properties of Thin-Film Field Emission Cathodes--;
Line 33, “with molybdenum cones”,” should read --with Molybdenum Cones”,--;
Line 35, “tunnel-emission amplifier”,” should read --Tunnel-Emission
Amplifier”,--; and
Line 45, “In ₂O₃/SnO₂” should read --In₂O₃/SnO₂--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 518364v1

PATENT NO. 6,890,231 B2

No. of add'l. copies
@ 30¢ per page



FEB 15 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,890,231 B2

DATED : May 10, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5

Line 25, "incorporation" should read --incorporating--.

COLUMN 6

Line 46, "manometer" should read --nanometer--.

COLUMN 8

Line 66, "an" should read --a--.

COLUMN 9

Line 65, "greater" should read --greater than--.

COLUMN 10

Line 38, "to" should read --to as--.

COLUMN 11

Line 28, "cross sectional" should read --cross-sectional--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 518364v1

PATENT NO. 6,890,231 B2

No. of add'l. copies
@ 30¢ per page



FEB 15 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,890,231 B2

DATED : May 10, 2005

INVENTOR(S) : TOSHIKAZU OHNISHI ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15

Line 3, "denotes" should read --denote--; and
Line 66, "byway" should read --by way--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 518364v1

PATENT NO. 6,890,231 B2

No. of add'l. copies
@ 30¢ per page



FEB 15 2006